

## Mine Inspection Record(s)

## [Go Back]

Information presented on this page is from inspections conducted by Mined Land staff and stored in our database. Note that there may be a drop-down list of multiple inspection dates available. Due to changes in data management practices over time, older inspection records are not as complete as new ones. Regarding inspections conducted specifically at the reclamation stage, some older reclamation information may be found here. However, newer more detailed reclamation inspection records can be found under the "Reclamation Inspections" link off the main Mines Data Search.

## Help for General Inspections General Search Tips

Company Name	It's Greener Now Inc		
Mine Name	Padua Mine		
Mine ID	80244		
Inspection Type	Old Gen. Inspection Code		
Inspector	Daniel Sek		
Inspection Date	11/22/2013	View	
Weather	clear		
Persons Interviewed			
Comments	Area outside the approved Life of Mine (southern portion of mine near cemetary) has not been reclaimed as agreed to in consent order, area is void of vegetation and minimal if any grading work. Berms at the eastern portion of mine (adjacent to Village stormwater ditch) continue to not be properly vegetated, Berm is in place but downslope sections have rilling and washouts. Berms must be vegetated to stabilize berm and minimize rilling, washouts and erosion. Berms must be seeded asap as weather permits. Currently excavating western face and has dug deeper to what appears to be ground water (photos taken). As stated in the approved plans- this area will be backfilled to a minimum of 5 feet above ground water table and will not be re-affected.		
Description	Result	Comments	
Permit posted	Yes		

Permit current	Yes	
Within permitted area	No	See Consent Order
Within LOM	No	See Consent Order
Setbacks OK	Yes	
Mining OK with plans	No	Vegetate Berms and %' seperation of groundwater and bedrock
Overburden/spoil piles ok	Yes	
Adequate topsoil	Yes	
Haul roads OK	Yes	
Dust control OK	Yes	
Noise control	Yes	
Drainage OK	No	Unvegetated Berms causing erosion/stormwater to exit mine limits
Screening in place	Yes	
Screening OK	No	Unvegetated
Entrance road OK	Yes	
Special conditions met	No	Conformance with plans violation
Operational	Yes	