



**Department of  
Environmental  
Conservation**

## Mine Inspection Record(s)

[\[Go Back\]](#)

Information presented on this page is from inspections conducted by Mined Land staff and stored in our database. Note that there may be a drop-down list of multiple inspection dates available. Due to changes in data management practices over time, older inspection records are not as complete as new ones. Regarding inspections conducted specifically at the reclamation stage, some older reclamation information may be found here. However, newer more detailed reclamation inspection records can be found under the “Reclamation Inspections” link off the main Mines Data Search.

[Help for General Inspections](#)  
[General Search Tips](#)

<b>Company Name</b>	<a href="#">It's Greener Now Inc</a>
<b>Mine Name</b>	Padua Mine
<b>Mine ID</b>	80244
<b>Inspection Type</b>	Old Gen. Inspection Code
<b>Inspector</b>	Joseph Bucci
<b>Inspection Date</b>	12/21/2010 <input type="button" value="View"/>
<b>Weather</b>	30's, overcast
<b>Persons Interviewed</b>	Martin Wojcik
<b>Comments</b>	Inspectors: Joe Bucci, Steve Army, Dan Sek; Comments: Mining program staff met with Mr. Wojcik at the IGN mine site to discuss the permit renewal application and the acreage that has been affected outside the Life of Mine. In previous documents submitted as a part of the renewal application, the acreage disturbed outside the approved Life of Mine was to be added to the operation, requiring a permit modification. After discussion, Mr. Wojcik wants to renew the permit only, and will reclaim the acreage affected outside the LOM. Mining program staff inspected the mine and documented the violation. Measurements and photos were taken of all acreage affected outside approved mining limits. The map submitted as a part of the renewal application accurately represents current site conditions (including acreage affected outside the LOM). Mr. Wojcik was reminded that he no longer operate since his mining permit expired on November 16, 2009 and their renewal application was not

submitted in a timely manner. Mr. Wojcik plans to have his consultants (Fagan Engineers) finish up the renewal application. Once the permit is re-issued, mining can commence.

<b>Description</b>	<b>Result</b>	<b>Comments</b>
Permit posted	Yes	
Permit current	No	Expired November 16, 2009.
Within permitted area	No	
Within LOM	No	
Setbacks OK	No	
Mining OK with plans	No	
Overburden/spoil piles ok	Yes	
Adequate topsoil	Yes	
Haul roads OK	Yes	
Dust control OK	Yes	
Noise control	Yes	
Drainage OK	Yes	
Screening in place	Yes	
Screening OK	Yes	
Entrance road OK	Yes	
Special conditions met	No	
Operational	No	