



**Department of
Environmental
Conservation**

Mine Inspection Record(s)

[\[Go Back\]](#)

Information presented on this page is from inspections conducted by Mined Land staff and stored in our database. Note that there may be a drop-down list of multiple inspection dates available. Due to changes in data management practices over time, older inspection records are not as complete as new ones. Regarding inspections conducted specifically at the reclamation stage, some older reclamation information may be found here. However, newer more detailed reclamation inspection records can be found under the “Reclamation Inspections” link off the main Mines Data Search.

[Help for General Inspections](#)
[General Search Tips](#)

Company Name	It's Greener Now Inc
Mine Name	Padua Mine
Mine ID	80244
Inspection Type	Old Gen. Inspection Code
Inspector	Steven Army
Inspection Date	05/31/2013 <input type="button" value="View"/>
Weather	P-Sunny
Persons Interviewed	Toni - Scale House Pit Manager
Comments	Site inspected to check the status of the reclamation of the area excavated outside the LOM along the southern pit boundary. The area remains untouched, and no reclamation has been done. I explained what needed to be done to the pit operator, and informed him that they were in violation of the consent order, and the work needed to be done immediately. Also spoke with Toni at the scale house and explained the same thing. Asked Toni to have Marty call me to discuss.. Site was dusty at the time of inspection. Haul road was dry, and dust was leaving the site. Had them run the water truck.

Description	Result	Comments
Permit posted	Yes	
Permit current	Yes	

Within permitted area	No	Area outside the LOM has not been reclaimed.
Within LOM	No	Area outside the LOM has not been reclaimed.
Setbacks OK	No	Area outside the LOM has not been reclaimed.
Mining OK with plans	No	Area outside the LOM has not been reclaimed.
Overburden/spoil piles ok	Yes	
Adequate topsoil	Yes	
Haul roads OK	No	Dust leaving the site.
Dust control OK	No	Dust leaving the site from haul road.
Noise control	Yes	
Drainage OK	Yes	
Screening in place	Yes	
Screening OK	Yes	
Entrance road OK	No	Dust and material leaving the site.
Special conditions met	No	
Operational	Yes	