



**Department of  
Environmental  
Conservation**

## Mine Inspection Record(s)

[\[Go Back\]](#)

Information presented on this page is from inspections conducted by Mined Land staff and stored in our database. Note that there may be a drop-down list of multiple inspection dates available. Due to changes in data management practices over time, older inspection records are not as complete as new ones. Regarding inspections conducted specifically at the reclamation stage, some older reclamation information may be found here. However, newer more detailed reclamation inspection records can be found under the “Reclamation Inspections” link off the main Mines Data Search.

[Help for General Inspections](#)

[General Search Tips](#)

<b>Company Name</b>	<a href="#">It's Greener Now Inc</a>
<b>Mine Name</b>	Padua Mine
<b>Mine ID</b>	80244
<b>Inspection Type</b>	Old Gen. Inspection Code
<b>Inspector</b>	Daniel Sek
<b>Inspection Date</b>	10/19/2017 <input type="button" value="View"/>
<b>Weather</b>	
<b>Persons Interviewed</b>	
<b>Comments</b>	Inspection of the reclamation of areas under consent order. The slopes are acceptable and topsoiled, site was hydroseeded and is now fully vegetated. Consent order is closed. Perimeter berms were hydroseeded also, but has not come up sufficiently to control erosion of the berms. Will need to verify veg is growing and determine if more seeding is needed. Will re-inspect in a few weeks,

Description	Result	Comments
Permit posted	Yes	
Permit current	Yes	
Within permitted area	Yes	
Within LOM	Yes	
Setbacks OK	Yes	

Mining OK with plans	Yes	
Overburden/spoil piles ok	Yes	
Adequate topsoil	Yes	
Haul roads OK	Yes	
Dust control OK	Yes	
Noise control	Yes	
Drainage OK	No	berms not vegetated, seed has yet to establish
Screening in place	Yes	
Screening OK	Yes	
Entrance road OK	Yes	
Special conditions met	Yes	
Operational	Yes	